Owner Name and Address: Fraser Oil Inc PO Box 770 Inverness MT 59530 Phone: (406) 292-3833

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5102311	Fraser Oil Inc Galata	US Highway 2 N	Galata	59444	(406) 432-2321

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	1126	10/1/1992 13 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H 1 J K L  B D E F G H 1 • K L	Yes Yes Yes Yes
4 / 04 Currently in Use	1127	10/1/1992 13 / No	Diesel 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCOEFGH)JKU B DEFGH)OKU	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5109152	Malmstrom AFB Q 11	Road 366	Rural Location	NZ051		

TankID/Alt TankID Status	Tag Installe Numbe Age/AS		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	<b>332</b> 5/2/1966	Diesel	Epoxy Coated Steel	Bare Steel	U.S. Suction	(ABCD@FGH)JKL	Yes
Currently in Use	40 / I	lo 11,000	Impressed Current	Impressed Current		(B D@FGH)JKL	Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys F	ac I	Location Name	Location Street Address	Location City	Zip	Location Phone
510	09153	Malmstrom AFB Q 12	Road 366	Rural Location	NZ051	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>333</b> 5/2/1966 40 / No	Diesel 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	ABCD • F G H   J K L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	<b>K</b> Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5109154	Malmstrom AFB Q 13	Road 218	Rural Location	NZ051	_	•

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	<b>334</b> 5/2/1966	Diesel	Epoxy Coated Steel	Bare Steel	U.S. Suction	ABCD@F@H]J&U	Yes
Currently in Use	40 / No	11,000	Impressed Current	Impressed Current		B D@F@H]J&U	Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address		<b>Location City</b>	Zip	Location Phone
5109155	Malmstrom AFB Q 14	Road 218	_	Rural Location	NZ051	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	335	10/1/1995 10 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	B DEF.H.I.K.L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5109157	Malmstrom AFB Q 16	Road 366	Rural Location	NZ051		

TankID/Alt TankID Status	Tag Installed Numbe Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>336</b> 5/2/1966 40 / N	Diesel 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	8 0 0 F G H 1 J K L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5109160	Malmstrom AFB Q 19	Road 417	Rural Location	NZ051	

TankID/Alt TankID Status	N	stalled ge/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	<b>339</b> 5/2/1	1966 0 / No	Diesel 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	ABCD0FGH1JKL B D0FGH1JKL	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 7 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3709148	Malmstrom AFB P 8	Interstate 15	Shelby	59474	(406) 731-3174

TankID/Alt TankID Status	Tag Installe Numbe Age/As		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>268</b> 5/2/1966 40 /	Diesel No 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	8 0 F G H 1 J K L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
3709149	Malmstrom AFB P 9	Interstate 15	Shelby	59474	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>269</b> 5/2/1966 40 / No	Diesel 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	ABCD	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 23

Owner Name and Address: MRC Hi Noon LLC PO Box 7578 Missoula MT 59807 Phone: (406) 542-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5100104	Noons 573	211 6th Ave N	Shelby	59474	(406) 434-5882

TankiD/Alt TankiD Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4382	2/18/1972 34 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	ABCDEFGH•J&L B • EFGH•J&L	Yes Yes Yes Yes
2 / 02 Currently in Use	3557	2/18/1972 34 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGH•JKL B • EFGH•JKL	Yes Yes Yes Yes
3 / 03 Currently in Use	4383	2/18/1972 34 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGH•JKL B • EFGH•JKL	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 23

Owner Name and Address: Ben Taylor Inc PO Box 810 Shelby MT 59474 Phone: (406) 434-5546

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5106113	Main Street Exxon	101 E Main St	Shelby	59474		

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 06 Currently in Use	426	8/16/1989 16 / No	Gasoline 8,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
7 / 07 Currently in Use	427	8/16/1989 16 / No	Gasoline 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEF.H)JKL B (BEFGH)JKL	Yes Yes Yes Yes
8 / 08 Currently in Use	428	8/16/1989 16 / No	Diesel 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEF.H)JKL B (BFGH)JKL	Yes Yes Yes Yes
9 / 09 Currently in Use	429	8/16/1989 16 / No	Gasoline 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEF.H)JKL (B • EFGH)JKL	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 23

Owner Name and Address: Greg and Shawn Matteson LLC 841 Marias Avenue Shelby MT 59474 Phone: (406) 434-2671

Sys Fac I	Location Name	Location Street Address	Loc	cation City	Zip	Location Phone	
5107144	Bryans Auto Repair	400 Main St	She	elby	59474	(406) 434-2671	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of U	<b>3940</b> Jse	12/21/1988 17 / No	Gasoline 2,000	STI-P3 None	Galvanized Steel Cathodically Protected	Safe Suction	B DEFGHIJKL B DEFGHIJKL	Yes Yes Yes Yes
2 / 02 Temporarily Out of U	<b>3941</b> Jse	12/30/1986 19 / No	Diesel 2,000	STI-P3 None	Galvanized Steel Cathodically Protected	Safe Suction	B DEEGH 1 O K C	Yes Yes Yes Yes
5 / 05 Currently in Use	1489	5/1/1991 15 / No	Used Oil 500	Fiberglass Reinforced Plastic None	Unknown None	Not Listed	<pre>     B</pre>	Yes Yes Yes No

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 23

Owner Name and Address: Simons Petroleum Inc 530 Roosevelt Highway Station PO Box 644 Shelby MT 59474 Phone: (406) 434-2431

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5108629	Simons Petroleum Inc 5108629	530 W Roosevelt Highway	Shelby	59474	(406) 434-2461	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
7 / 07 Currently In Use	5014	5/27/2005 01 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF 6 H 1 J K L	No Yes Yes Yes
8 / 08 Currently In Use	5015	5/27/2005 01 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B DEFOHIJKL	No Yes Yes Yes
9 / 09 Currently In Use	5012	5/27/2005 01 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B DEFOHIJKL	No Yes Yes Yes
10 / 10 Currently In Use	5013	5/27/2005 01 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC • E F G H 1 J K L) (B D E F • H 1 J K L)	No Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5109141	Malmstrom AFB P 1	Interstate 15	Shelby	59474	

TankID/Alt TankID Status	Tag Installe Numbe Age/AS		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>327</b> 5/2/1986 20 /	Diesel No 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	(ABCD@F@H)J&L (B D@F@H)J&L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5109150	Malmstrom AFB P 10	Interstate 15	Shelby	59474	

TankID/Alt TankID Status	Tag Install Age/A		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>328</b> 5/2/1966 40 /	Diesel No 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	ABCDEFGHIJKL B DEFGHIJKL	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 15 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5109158	Malmstrom AFB Q 17	Road 417	 Shelby	59474	

TankID/Alt TankID Status	Tag Installed Numbe Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>337</b> 5/2/1966 40 / No	Diesel 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	ABCD0FGHJ&L           B D0FGHJ&L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 16 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5109159	Malmstrom AFB Q 18	US Highway 2	Shelby	59474	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	<b>338</b> 5/2/1966	Diesel	Epoxy Coated Steel	Bare Steel	U.S. Suction	ABCD0FGH1JKL	Yes
Currently in Use	40 / No	11,000	Impressed Current	Impressed Current		B D0FGH1JKL	Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 23

**Owner Name and Address:** 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone	
5109161	Malmstrom AFB Q 20	US Highway 2	Shelby	59474		<u>-</u> '

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	<b>340</b> 5/2/1966 40 / No	Diesel 11,000	Epoxy Coated Steel Impressed Current	Bare Steel Impressed Current	U.S. Suction	B D @ F G H 1 J K L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 18 of 23

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
5109749	Town Pump Inc Shelby	1350 Roosevelt Highway	Shelby	59474	(406) 434-5221

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2657	9/7/1988 17 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	2658	9/7/1988 17 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH)JKL (B DEFOH)JKL	Yes Yes Yes Yes
3 / 03 Currently in Use	2659	9/7/1988 17 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	4291	9/7/1988 17 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	4292	9/7/1988 17 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJK) B (DEFOHIJK)	Yes Yes Yes Yes
6 / 06 Currently in Use	4293	8/1/1992 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)JKL (B DEFOH)JKL	Yes Yes Yes Yes
7 / 07 Currently in Use	2663	8/1/1992 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH)JKL B DEFOH)JKL	Yes Yes Yes Yes
8 / 08 Currently In Use	4248	7/1/1999 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized		Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging C Invent	tory Control E Vapor Monit	toring G Interstit, Dbl-Wall Monitor	I SIR	K Deferred	
	,	9		L Not Listed	

9 / 09 Currently In Use **4413** 10/1/2001 Diesel 04 / No 20,000

Fiberglass Reinforced Plastic Double-Walled

Flexible Plastic None Not Listed

ABCOEFOHIJKL B DEFGHIJKL

Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank GaugingC Inventory ControlE Vapor MonitoringG Interstit. Dbl-Wall MonitorI SIRK DeferredB Tank/Line Tightness TestingD ATG/Auto Line LDF GW MonitoringH Interstit. Sec. Con. MonitorJ Other MethodsL Not Listed

Report Generation Date: 7/3/2006 Page 20 of 23

Owner Name and Address: Ben Taylor Inc PO Box 810 Shelby MT 59474 Phone: (406) 434-5546

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5102025	Taylors Bulk Plant	55 Railroad Ave	Sunburst	59482	(406) 937-2161

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / S6 Currently In Use	4137	8/31/1999 06 / Ye	Gasoline 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGH1J&L B DEF•H1J&L	Yes Yes Yes Yes
7 / S7 Currently In Use	4138	8/31/1999 06 / Ye	Gasoline 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	B DEF GH ] J & L	Yes Yes Yes Yes
8 / S8 Currently In Use	4139	8/31/1999 06 / Ye	Diesel 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEF6H) B (DEF.H)	Yes Yes Yes Yes
9 / S9 Currently In Use	4140	8/31/1999 06 / Ye	Diesel 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH) J. (L) B (DEF. H) J. (L)	Yes Yes Yes Yes
10 / S10 Currently In Use	4161	8/31/1999 06 / Ye	Diesel 1,500	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH) J&L B (DEF ) H) J (K)	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 21 of 23

Owner Name and Address: Ammex Tax & Duty Free America 6100 Hollywood Blvd Hollywood FL 33024 Phone: (954) 986-7700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5101377	Sweetgrass Speedy Mart	2 Main St	Sweet Grass	59484	(406) 335-2802

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 03 Currently in Use	871	1/1/1990 16 / No	Gasoline 15,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL BOEFGHIJKL	No Yes Yes Yes
3 / 04 Currently in Use	872	1/1/1990 16 / No	Gasoline 15,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	No Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 22 of 23

Owner Name and Address: Paper Dollar Bar Inc PO Box 110 Sweet Grass MT 59484 Phone: (406) 335-2905

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5112405	Paper Dollar Bar Inc	510 2nd St	Sweet Grass	59484	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2718	6/25/1991 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H   J K L B • E F G H   J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	2719	6/25/1991 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))KL (BOEFGH))KL	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 23 of 23